

02/03/2017

Submittal of 3/4" Crushed Rock

The following is submitted for your review and acceptance:

3/4" Crushed Rock-1816

Procedure	Sieve/Test	Average	Unit	Granite
CT 202	1"	100	%	100-100
CT 202	3/4"	96	%	90-100
CT 202	1/2"	24	%	10-55
CT 202	3/8"	3	%	0-15
CT 202	#4	1	%	0-5
CT 202	#200	0.6	%	
CT 202	PAN	0.0	%	
CT 206	SPGR (Dry)	2.813		>2.60
CT 206	Absorption	0.6	%	<3
CT 227	CV	89		>60
CT 205	Fractured Faces (>2)	90.0		>75

If we can be of further assistance, please do not hesitate to contact us.

Respectfully,
GRANITE CONSTRUCTION COMPANY*Expires 12 months from date of issue*